

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-06-11
As a result of Inspection 2026-2021

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0386-01</p> <p>Issued Date: '2026-06-16'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-30'</p>	<p>Permit: 100056753 Road Number: 01187 Segment IDs (Location): 001 (From NTS: A- 063-G/094-B-08 To NTS: C- 054-G/094-B-08)</p> <p>Legislation: Energy Resource Road Regulation</p> <p>Subject to section 15, a road permit holder must perform the maintenance and undertake the modifications necessary to ensure that (b) the road prism and all access structures related to the road are stable,</p>
---	---

Non-Compliance Comment: The correction time for this deficiency is system generated. It is likely more time will be needed to identify the problem and take corrective action.

The non-compliance are the tension cracks showing instability in the road bed and moving towards the active travel path. The ditch has eroded more but there is a culvert that was buried when earth works were completed in the last few years and this could also be involved in the tension cracks if it is undermined or interfered with road bed compaction.

Photos will be uploaded in the inspection.

<p>Non-Compliance Number: 2026-0386-02</p> <p>Issued Date: '2026-06-16'</p>	<p>Permit: 100056753 Road Number: 01187 Segment IDs (Location): 001 (From NTS: A- 063-G/094-B-08 To NTS: C- 054-G/094-B-08)</p> <p>Legislation: Environmental Protection and Management Regulation</p>
---	--

<p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-30'</p>	<p>12 A person who carries out an oil and gas activity on an operating area must ensure that the oil and gas activity does not result in any deleterious materials being deposited into a stream, wetland or lake.</p>
<p>Non-Compliance Comment: The deficiency timeframe is system generated and extra time may be required to assess the issue and collect resources. An extension could be granted.</p> <p>The environmental issue is the amount of sediment, road construction dirt and gravel entering the stream. These can be seen in the photos. Some of the observations are as follows; there are no techniques to direct some of the sediment laden water out of the ditch before it enters the stream, there were no techniques deployed to slow the water moving in the ditch, the earthworks were not revegetated. Earlier in this spring it was noted surface run off into the ditch on the up chain side started at the junction at the next road which is approximately 500 meters away.</p> <p>Most of the sediment issue is on on the up chain side of the bridge, however the other side needs to be assessed.</p> <p>As noted in the inspection details, this stream is a tributary to Groundbirch Creek which has sportfish populations of rainbow and bull trout as well as arctic grayling.</p>	

Authorized by BCER