

## Inspection Report

Permit Holder: Cedar LNG Partners (GP) Ltd.

Inspection: 2025-4985

Inspection Date: 2025-12-04

Inspection Outcome: Inspected

### Inspection Comment:

Joint inspection with Haisla Nation completed December 04, 2025. Site demobilized for winter shutdown. Recommencement of activities planned in spring 2026.

#### Road 4.7

- \* Road temporarily closed for winter shutdown, rig mats stacked at start of road. Discussed notification and signage.
- \* Road capped since previous inspection, additional rock placed in ditchline. Ditch water running clear at time of inspection.
- \* Transmission line clearing complete in area. Transmission line conventional clearing for entire project complete, heli logging approximately 75% complete.

#### Road 4.07 (WC-1.5 - S6)

- \* Road capped, ESC at crossing keyed in well.
- \* Stream free of large woody debris from clearing activities, water running clear at time of inspection.

#### WC-01 (S6)

- \* Filter cloth lined sump installed in ditchline above crossing. Noted sump approximately half full at time of inspection. Pumps have been removed from site. Discussed potential ESC response plans during shutdown and winter monitoring plan. Cedar LNG staff informed BCER that site monitoring will occur periodically and after rainfall events, with water quality testing occurring based on rainfall amounts (25mm over 1 day or 60mm over 3 days).

#### Road 5A

- \* Road barricaded just beyond watercourse crossing.
- \* WC-06 (S6) running clear, ESC keyed in well. Big O passively moving ditchline water to vegetation beyond stream.

#### AC-11 (S3) - Road 5

- \* Viewed road, stream, and discussed recent exceedance notifications. Noted general area is low lying. Cedar LNG road permit and separate non-project

industrial workspace join. Non-project industrial waterline located in area, limiting ESC installation locations. Some sediment laden water from non-project workspace running onto Road 5.

\* Lined sump installed for settling, big O pipe directing overflow away from stream and into vegetation. Noted minor sediment in vegetation. Area to be monitored, potential raking in spring may be required.

\* AC-11 running clear at time of inspection.

#### Marine Terminal Topsoil Storage Area

\* Additional hydroseed applied since last inspection, seed establishing well.

\* ESC maintenance required as per previous inspection completed, and additional ESC installed along eastern and southern perimeters.

\* Upper perimeter drainage improved, water running around topsoil pile and not making contact. All water leaving site clear at time of inspection.

\* Significant improvements completed to manage water and reduce contact with topsoil.

#### Marine Terminal

\* Additional hydroseed applied in various areas since previous inspection. Seed establishing well.

\* All sumps now lined with snow fencing. Sumps holding water, sediment settling in sumps.

\* Additional poly/geo installed on exposed soils. Estimated 90% of exposed soils on site are currently covered.

\* Lower ditchline for northern access road lined with poly. Water running clear, no longer in contact with exposed soils.

\* WC-18B.1 (S6) - Additional wattles and double layer silt fencing installed.

\* All watercourses observed running clear. All water leaving site running clear.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100117155

Road Number: 06613

Segment IDs (Location): 003 (From NTS: D- 038-B/103-I-02 To NTS: D- 038-B/103-I-02), 005 (From NTS: D- 038-B/103-I-02 To NTS: B- 038-B/103-I-02), 006 (From NTS: C- 028-B/103-I-02 To NTS: A- 038-B/103-I-02)

Permit: 100117157

Road Number: 06615

Segment IDs (Location): 001 (From NTS: A- 077-J/103-H-15 To NTS: C- 066-J/103-H-15)

Permit: 100117229  
Road Number: 06607  
Segment IDs (Location): 001 (From NTS: C- 017-B/103-I-02 To NTS: B- 027-B/103-I-02), 002 (From NTS: B- 027-B/103-I-02 To NTS: C- 017-B/103-I-02)

Permit: 100117231  
Road Number: 06606  
Segment IDs (Location): 001 (From NTS: A- 048-B/103-I-02 To NTS: B- 047-B/103-I-02), 002 (From NTS: A- 038-B/103-I-02 To NTS: A- 048-B/103-I-02)

Permit: 100116060  
AACT Number: 00225031  
Site Type: Workspace

Permit: 100117231  
AACT Number: 00229922  
Site Type: Access

Permit: 100117155  
CIAS Number: 0007899  
Location ID (Crossing Type): 16 (Culvert)

Permit: 100117231  
CIAS Number: 0007878  
Location ID (Crossing Type): 83 (Culvert)

Permit Holder: Cedar LNG Partners (GP) Ltd.

---

Authorized by BCER