

Inspection Report

Permit Holder: Coastal GasLink Pipeline Ltd.
Inspection: 2026-0871
Inspection Date: 2026-02-11
Inspection Outcome: Inspected

Inspection Comment:

Inspection of Cedar Link Connector project area completed after significant rain event and high Kitimat River water levels near site.

- * Impacts from previous Kitimat River side channel flooding observed, specific flooded areas now identified as "Pond 1", "Pond 2", and "Pond 3". All three ponds observed by inspectors.
- * Fish salvage by Qualified Professionals on all ponds complete.
- * Discussed frequency of site monitoring by permit holder. BCER informed that site is visited at least twice per day to monitor pump off area, and increased frequency during significant rainfall events.
- * Hoselay attached to connector on bund wall confirmed to be pump off from metering station.
- * Viewed pump off locations. Multiple pumps to manifold which splits into a series of filter bags. Location appears to be managing water well. Regular maintenance occurs and filter bag replaced as/when needed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100117544
AACT Number: 00229756
Site Type: Workspace

Permit: 100117544
AACT Number: 00229759
Site Type: Workspace

Permit: 100117544

Permit Holder: Coastal GasLink Pipeline Ltd.

Authorized by BCER



Inspection Number: 2026-0871
Inspection Date: 2026-02-11

Letter ID: L2601269
Letter Date: 2026-03-13