

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1560
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Inspect access and access signage.

Note Water Source #50 has damaged fencing. See attached pictures.

Inspect wells A-C. No SCV flow observed. Wellheads barricaded. Signage clear and legible. Meters inspected. B well has some planks, a strap and cord laying near well (picture attached). Spoke with operator who cleaned up same day.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038280
Well ID: 16106
Well Name: OVV HZ SUNDOWN B-A045-L/093-P-08
Location: NTS: B-A045-L/093-P-08

Permit: 100042790
Well ID: 17860
Well Name: OVV HZ SUNDOWN B-C045-L/093-P-08
Location: NTS: B-C045-L/093-P-08

Permit: 100043067
Well ID: 17806
Well Name: OVV HZ SUNDOWN B-B045-L/093-P-08
Location: NTS: B-B045-L/093-P-08

Permit: 100038280
Facility ID: 00020165
Facility Name: OVV DEEPBASIN B-045-L/093-P-08 001
Facility Type: Well Facility
Location: NTS: B- 045-L/093-P-08

Permit: 100042790
Facility ID: 00020697
Facility Name: OVV DEEPBASIN B-045-L/093-P-08 002
Facility Type: Well Facility
Location: NTS: B- 045-L/093-P-08

Permit: 100043067
Facility ID: 00020675
Facility Name: OVV DEEPBASIN B-045-L/093-P-08 003
Facility Type: Well Facility
Location: NTS: B- 045-L/093-P-08

Permit: 100058206
Road Number: 00502
Segment IDs (Location): 001 (From NTS: B- 045-L/093-P-08 To NTS: D- 060-L/093-P-08)

Permit: 100058206
AACT Number: 00023877
Site Type: Aggregate Operations / Borrow Pit

Authorized by BCER