

Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-1662
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1335HRS.

Access road- Vegetation growing on access road. Road has rutted tire tracks in areas. No concerns at the time of inspection.

Lease environment- Vegetation and limited woody debris on lease. No erosion sediment or water runoff concerns.

Lease Equipment: All Wellheads Abandoned. Surface equipment removed from site. No signage in place. Locations looks to have recently (in last year) had groundwork completed (see attached). No concerns at the time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100021161
Well ID: 10757
Well Name: STRATHCONA RIGEL 16-14-088-18
Location: DLS: 16-14-088-18

Permit: 100022505
Well ID: 11403
Well Name: STRATHCONA ET AL HZ RIGEL B16-14-088-18
Location: DLS: B16-14-088-18

Permit: 100026004
Well ID: 12748
Well Name: STRATHCONA HZ RIGEL C16-14-088-18
Location: DLS: C16-14-088-18



Permit: 100026281
Well ID: 12833
Well Name: STRATHCONA ET AL HZ RIGEL D16-14-088-18
Location: DLS: D16-14-088-18

Authorized by BCER