

## Inspection Report

Permit Holder: Strathcona Resources Ltd.  
Inspection: 2026-1682  
Inspection Date: 2026-05-21  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Officer Selected Informed inspection of surface equipment on site.

Performed inspection of location at 1600HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well: Wellhead Abandoned. location was a former injection site. Surface equipment removed from site. Signage in place at lease entrance (faded) and at well. Signage post falling into collapsed pit around where wellhead was abandoned (See attached). Various garbage and debris located around location.

Please contact Compliance Officer via email to discuss future plans for location.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100017378  
Well ID: 09327  
Well Name: STRATHCONA RIGEL 10-27-088-18  
Location: DLS: 10-27-088-18

---

Authorized by BCER