

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-1706
Inspection Date: 2026-05-22
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-location signage at the beginning of the lease road is missing the flammable symbol. Location signage at the lease has a faded emergency number. Guarding around wellhead.

-wellhead valves chained and locked. Flowline is disconnected from the wellhead. Equipment remains in place.

lease and access are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016163
Well ID: 08831
Well Name: CANLIN BOUNDARY A08-05-085-14
Location: DLS: A08-05-085-14

Authorized by BCER