

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-1792
Inspection Date: 2026-05-28
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead only, valves chained and locked. Flowline is disconnected from the wellhead. Fencing around wellhead. No SCVF

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001925
Well ID: 01454
Well Name: CANLIN BOUNDARY A06-24-085-14
Location: DLS: A06-24-085-14

Permit: 100001925
Facility ID: 00018513
Facility Name: CANLIN BOUNDARY LAKE 06-24-085-14 002
Facility Type: Well Facility
Location: DLS: 06-24-085-14

Authorized by BCER