

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-1796
Inspection Date: 2026-05-28
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead only, valves chained and locked. Flowline is disconnected from the wellhead.

-Pumpjack frame remains in place. No SCVF

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100004365
Well ID: 03219
Well Name: CANLIN BOUNDARY A16-24-085-14
Location: DLS: A16-24-085-14

Authorized by BCER