

Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-1999
Inspection Date: 2026-06-10
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

COMMENTS:

7-3-86-18:

-wellhead only with a cover.

-the flowline is disconnected from the wellhead, but the wellhead valves are not chained and locked as per the D&PR for a surface suspended well. Please lock and chain or remove the wellhead valve handles to achieve proper surface suspension requirements. Contact me once completed.

-No SCVF

A7-3-86-18:

-wellhead valve handles removed. Flowline is disconnected from the wellhead. Meter building and piping remain in place.

-No SCVF. Guarding around wellhead.

-lease and access are compliant.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100013754
Well ID: 07963
Well Name: STRATHCONA ET AL OAK 07-03-086-18
Location: DLS: 07-03-086-18

Permit: 100020903
Well ID: 10641
Well Name: STRATHCONA ET AL OAK A07-03-086-18
Location: DLS: A07-03-086-18

Permit: 100013843
Facility ID: 00001093
Facility Name: OAK 07-03-086-18 001
Facility Type: Battery Site
Location: DLS: 07-03-086-18

Authorized by BCER