

## Inspection Report

Permit Holder: Strathcona Resources Ltd.  
Inspection: 2026-2006  
Inspection Date: 2026-06-10  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

#### COMMENTS:

-Inactive electric pumpjack connected to the polish rod. Wellhead valve handles removed and flowline is disconnected from the wellhead.

-guarding around wellhead. No SCVF

-lease and access are compliant.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100013941  
Well ID: 08021  
Well Name: STRATHCONA ET AL OAK 03-03-086-18  
Location: DLS: 03-03-086-18

Permit: 100014056  
Facility ID: 00001131  
Facility Name: OAK 03-03-086-18 001  
Facility Type: Battery Site  
Location: DLS: 03-03-086-18

---

Authorized by BCER