

Inspection Report

Permit Holder: LNG Canada Development Inc.

Inspection: 2026-2430

Inspection Date: 2026-07-09

Inspection Outcome: Inspected

Inspection Comment:

Inspection of LNG Canada warm/wet flare tip on July 9, 2026.

- * Flare tip has been positioned near base of flare stack following removal.
- * Flare tip has a visible crack on the upper side of arm joint. Similar joints throughout the structure also exhibit areas of potential metal loss and fatigue.
- * Discussed investigation process and replacement strategy.
- * Replacement flare tip is on site and crews are preparing for installation.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit Holder: LNG Canada Development Inc.

Authorized by BCER