

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-2919

Inspection Date: 2026-08-13

Inspection Outcome: Inspected

Inspection Comment:

This follow up inspection is for the Altares Road at the bridge stream crossing close to the km 6 marker. The corrections have been made to the erosion issues that were found in June. There are straw waddles and coconut matting installed plus a take off on the up-chain and upstream ditch. For some reason the coconut matting stops before this take off and there is no measures in place to slow the water down as it leaves the ditch. There is one sediment fence that has partly collapsed and water is flowing over top of it. The measures taken to address the erosion are going to require regular maintenance as such this stream crossing will continue to be on a follow up list for inspections.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100102099

Road Number: 04427

Segment IDs (Location): 001 (From NTS: C- 008-I/094-B-08 To NTS: B- 063-G/094-B-08)

Authorized by BCER