

Inspection Report

Permit Holder: Enercapita Energy Ltd.
Inspection: 2026-2945
Inspection Date: 2026-08-14
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- wellhead valves chained and locked. Flowline is disconnected from the wellhead. Pumpjack remains in place disconnected. Polish rod removed.
- No SCVF
- lease and access are becoming overgrown with vegetation and trees.
- location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100010213
Well ID: 06876
Well Name: ENERCAPITA N BOUNDARY 14-30-087-14
Location: DLS: 14-30-087-14

Permit: 100010213
Facility ID: 00018967
Facility Name: ENERCAPITA BOUNDARYLAKENORTH 14-30-087-14 001
Facility Type: Well Facility
Location: DLS: 14-30-087-14

Permit: 100010846
Facility ID: 00000434
Facility Name: ENERCAPITA BOUNDARYLAKENORTH 14-30-087-14 002
Facility Type: Battery Site
Location: DLS: 14-30-087-14

Authorized by BCER



Inspection Number: 2026-2945
Inspection Date: 2026-08-14

Letter ID: L2604182
Letter Date: 2026-08-17