

## Non-Compliance Notice - Issued

Permit Holder: Pacific Canbriam Energy Limited  
 Discovery Date: 2026-04-30  
 As a result of Inspection 2026-1400

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0277-01</b></p> <p>Issued Date: <b>'2026-05-05'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>30 Days</b></p> <p>Correction Due Date: <b>'2026-06-04'</b></p>	<p>Permit: 100073877          Well ID: 27196          Well Name: PACIFIC CANBRIAM HZ ALTARES C- 023-H/094-B-08          Location: NTS: C- 023-H/094-B-08</p> <p>Legislation:          Energy Resource Activities Act          37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following:          (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: c-23-H well-bubbles are coming up thru the water filled cellar from both sides of the annulus valves. The correction period of 30 days has been chosen in order to remove the cellar grate and water.</p>	

<p>Non-Compliance Number: <b>2026-0277-02</b></p> <p>Issued Date: <b>'2026-05-05'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration:</p>	<p>Permit: 100073878          Well ID: 27242          Well Name: PACIFIC CANBRIAM HZ ALTARES C-A023-H/094-B-08          Location: NTS: C-A023-H/094-B-08</p> <p>Legislation:          Energy Resource Activities Act          37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following:          (a) remedy the cause or source of the spillage;</p>
--	---

<p><b>30 Days</b></p> <p>Correction Due Date: <b>'2026-06-04'</b></p>	
<p>Non-Compliance Comment: c-a-23 well-bubbles are coming up thru the water filled cellar and appear to be coming from the bull plug at the end of the annulus valves.</p>	

<p>Non-Compliance Number: <b>2026-0277-03</b></p> <p>Issued Date: <b>'2026-05-05'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-05-19'</b></p>	<p>Permit: 100080680 Well ID: 30579 Well Name: PACIFIC CANBRIAM HZ ALTARES C-D023-H/094-B-08 Location: NTS: C-D023-H/094-B-08</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (c) remediate any land or body of water affected by the spillage;</p>
<p>Non-Compliance Comment: There is a bunch of frac sand on the ground outside the sand filter containment bin. This needs to be cleaned up.</p>	

---

Authorized by BCER