

Non-Compliance Notice - Issued

Permit Holder: NTE Energy Canada Ltd.
Discovery Date: 2026-06-02
As a result of Inspection 2026-1812

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0339-01</p> <p>Issued Date: '2026-06-03'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-17'</p>	<p>Permit: 100039884 Well ID: 17191 Well Name: NTE CANADA HZ GUNNELL A-A028-J/094-I-13 Location: NTS: A-A028-J/094-I-13</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: The upper flowline ball valve injection port located adjacent to the wellhead is missing a bull plug.</p>	

<p>Non-Compliance Number: 2026-0339-02</p> <p>Issued Date: '2026-06-03'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p>	<p>Permit: 100039884 Well ID: 17191 Well Name: NTE CANADA HZ GUNNELL A-A028-J/094-I-13 Location: NTS: A-A028-J/094-I-13</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
---	---

Correction Due Date: '2026-06-17'	
Non-Compliance Comment: LEL gas was measured (Altaire-5x) at the wellhead lower wing valve handle/packing area. Note: Flowline plastic snake wrap/insulation is deteriorating and requires maintenance.	

Authorized by BCER