

## Non-Compliance Notice - Issued

Permit Holder: Yoho Resources Inc.  
Discovery Date: 2026-05-28  
As a result of Inspection 2026-1822

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0342-01</b></p> <p>Issued Date: <b>'2026-06-03'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-06-17'</b></p>	<p>Permit: 100103458 Facility ID: 00026550 Facility Name: YOHO INGA 11-24-087-24 001 Facility Type: Well Facility Location: DLS: 11-24-087-24</p> <p>Legislation: Drilling and Production Regulation 49 (2) Subject to subsection (1), a permit holder must lock or car seal any valve or device that can bypass or disable safety equipment at a well that is producing, injecting or disposing of fluids, or at a facility.</p>
<p>Non-Compliance Comment: In the line heater skid, the ball valve at the base of the piping for the fuel gas high pressure sensor (PSHH) needs to be locked in the open position. The needle valve above it is clamshelled in the open position. As an observation, this same piping has been changed for the fuel gas PSHH at the line heater at 3-14-87-23.</p>	

---

Authorized by BCER