

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-10-01
As a result of Inspection 2026-3459

Notice Comment:

The flow line is disconnected but the valve handles are not chained and locked or removed to prevent tampering.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0670-01 Issued Date: '2026-10-08' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-11-07'	Permit: 100071507 Well ID: 26470 Well Name: PETRONAS GUNDY D-B063-G/094-B-16 Location: NTS: D-B063-G/094-B-16 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well; Non-Compliance Comment: The well head does not have any valves chained and locked or removed.
---	--

Authorized by BCER