Inspection Report

Permit Holder: NorthRiver Midstream NEBC Connector GP Inc.
Inspection: 2026-3583
Inspection Date: 2026-10-30
Inspection Outcome: Inspected

Inspection Comment:
Inspection with the operator of the NEBC pipeline construction October 30, 2026.
AD 100118625, CIAS 08801.

KP 98+100, WC-145, S3, restored, armored banks, slopes have ECB and waddles in place, Channel is wet with beaver dams upstream and downstream. Cattle have moved through the area and have created ground disturbance on the stream slopes and ROW. Discussed with the operator about potential issues in the spring due to cattle. CIAS location 180.

KP 147+479, WC-194, NCD, restored, ECB and waddles. CIAS location 263.

KP 147+836, WC-195, NCD, HDD site, travel lane with pipe culvert and dirt fill. Site being restored at the time of the inspection. CIAS location 264.

KP 148+100, WC-195.05, NCD, travel lane has a pipe culvert with dirt fill, stream has been restored swale with ECB and waddles, riparian mostly intact. CIADS location 265.

KP 148+731, WL-395, rig matted crossing. CIAS location 266.

KP 150+050, WL-514, W2, permanently removed. CIAS location 267.

KP 183+200, Hydrotest dewatering location, private land plowed field and treed area, site was used approximately 2 weeks ago for dewatering lines from KP 216 to 183. At that time 1782 cubic meters from the 10" line and 2416 cubic meters from the 12" line was released after sampling. Hydrotest water was transferred through a 6" line to a splitter, (4 x 4") each 4" line going to a pig pen packed with straw bales and geo fabric diffuser. No erosion or standing / pooled water was observed at the time of the inspection.

KP 175+107, WC-211, S4, Doe Creek, clear-span bridge was pulled today, Restoration is being completed on the stream banks and channel. Hard wrap with posts on the banks and ECB on the slopes. Roadside has natural vegetation remaining. CIAS Location 294.

KP 175+107, WL-446, W2, follows WC-211, restoration is being completed on the affected portion with natural vegetation remaining on roadside. CIAS location 293.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118625
CIAS Number: 0008801
Location ID (Crossing Type): 180 (Flow Isolation), 263 (Flow Isolation), 264 ((HDD) Directional Drill), 265 (Flow Isolation), 266 (Matting), 267 (Flow Isolation), 293 (Flow Isolation), 294 (Flow Isolation)

Permit: 100118625

Permit Holder: NorthRiver Midstream NEBC Connector GP Inc.

_____

Authorized by BCER