

Inspection Report

Permit Holder: Lakota Operating Company Inc.
Inspection: 2026-3441
Inspection Date: 2026-10-01
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

COMMENTS:

-this inspection is from a complaint from the landowner in regard to weeds on the wellsite and concerns of spreading into his fields. After driving to this wellsite, I found that the wellsite is covered in Thistle and is now in the seed stage. This is something that should be addressed with the landowner and a plan put in place.

-Inactive electric pumpjack. Wellhead valves are chained and locked. Flowline is disconnected from the wellhead. Pumpjack remains in place connected to the polish rod.

-No SCVF

-some chemical remains in chemical tank

-lease covered in Thistle and should be addressed

-guarding around the wellhead area.

-gauges remain on the piping and the wellhead. Should be removed to meet surface suspension requirements.

-as per the Guidelines, a 10-meter radius around the wellhead should be free of vegetation on a suspended well. Therefore, weed control is required.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016025

Well ID: 08793

Well Name: LAKOTAOP TALLAHASSEE W FLATROCK 04-16-085-17

Location: DLS: 04-16-085-17

Permit: 100062020
Pipeline Project ID: 000000095
Segment IDs (Location): 1 (From DLS: 04-16-085-17 To DLS: 08-17-085-17)

Authorized by BCER