

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3482

Inspection Date: 2026-10-13

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead only, valves chained and locked.

-No SCVF. There is felt pen writing on the SCV that reads....Burst plate removed August 2021. My latex glove did not inflate, but each time I took the glove off of the SCV assembly, there would be a heard gurgle. This happened each time I put glove on and off of SCV assembly.

-lease is in a field with no access road. Lease is being farmed right up to and around the wellhead.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100007742

Well ID: 05441

Well Name: PETRONAS ET AL W FLATROCK 11-02-085-17

Location: DLS: 11-02-085-17

Authorized by BCER