

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3525
Inspection Date: 2026-10-15
Inspection Outcome: Inspected

Inspection Comment:

The broken matting should be removed. There are 3 lengths of steel (for mouse holes ?) that if not required for the next wells should be removed. There are also 2 short pieces of brown coated steel pipe in the same grouping. Other than the above, no concerns with the wells and equipment.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100109497
Well ID: 39723
Well Name: TOURMALINE HZ BLUEBERRY WEST A- 010-D/094-A-13
Location: NTS: A- 010-D/094-A-13

Permit: 100109497
Well ID: 39724
Well Name: TOURMALINE HZ BLUEBERRY WEST A-A010-D/094-A-13
Location: NTS: A-A010-D/094-A-13

Permit: 100109497
Well ID: 39725
Well Name: TOURMALINE HZ BLUEBERRY WEST A-B010-D/094-A-13
Location: NTS: A-B010-D/094-A-13

Permit: 100109497
Well ID: 39726
Well Name: TOURMALINE HZ BLUEBERRY WEST A-C010-D/094-A-13
Location: NTS: A-C010-D/094-A-13

Permit: 100109497
Facility ID: 00027094
Facility Name: TOURMALINE BLUEBERRY WEST A-010-D/094-A-13 001
Facility Type: Well Facility
Location: NTS: A- 010-D/094-A-13



Inspection Number: 2026-3525
Inspection Date: 2026-10-15

Letter ID: L2605064
Letter Date: 2026-10-22

Authorized by BCER