

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3552
Inspection Date: 2026-10-21
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

This is a follow up inspection for the original inspection 2023-2855. A deficiency was given regarding revegetating the disturbed area for the Mile 109 road widening at km 0. In 2024, effort was taken by Tourmaline to improve the ecologically suitable species composition away from alfalfa and clover. The deficiency response from Tourmaline was that the area was decompacted and planted with appropriate woody tree species. On October 21, 2026, this work was evaluated with an extensive walk thru.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100057613
Road Number: 00278
Segment IDs (Location): 016 (From NTS: C- 064-D/094-A-13 To NTS: C- 090-L/094-A-12)

Authorized by BCER