Inspection Report

Permit Holder: Trans Mountain Pipeline ULC
Inspection: 2026-3562
Inspection Date: 2026-10-07
Inspection Outcome: Inspected

Inspection Comment:
On October 7, 2026, BCER continued an inspection of Trans Mountain Pipeline ULC changes in and about a stream works in the Hope/Coquihalla corridor.

Inspection items:

* Road 10 5b minor reclamation kp1009.4 - minor works to remove sediment material from channel and remove debris from culvert. No flow at time of inspection.
* Road 10 5b minor reclamation 599a-S6 - minor reclamation works to remove sediment from hardened ford and streambank. Matted air bridge being utilized to gain machine access to down-chainage work area. No flow at time of inspection.
* Road 10 5b minor reclamation 599 - reclamation works on upper right portion of channel that had been eroded. sediment removed from channel, and small area reclaimed and seeded.
* Road 10 5b minor reclamation 598.2ncd - high side ditch reestablished and cleaned out. Downstream of culvert, sedimentation removed and topsoil material reclaimed and seeded. ECB added to stabilize topsoil material. No flow at time of inspection.
* Road 10 5b minor reclamation 598 - eroded area on left streambank reclaimed and seeded. ECB added for stabilization.
* Road 10 5b minor reclamation 600.1 - upper right channel erosion. Streambank reestablished and sediment removed. ECB added and seeded.
* Road 10 5b minor reclamation 603a - fallen tree altered channel. Hand work necessary to improve drainage and reestablish channel. Water flowing clean at time of inspection.
* Road 10 5b minor reclamation 605c - sediment to be removed from hardened ford and improve flow over access. Small areas of sloughing observed to fill high side ditch along access. Work is to be completed here in the coming days. No flow at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100123655
CIAS Number: 0011086
Location ID (Crossing Type): 8 (Gravel Removal), 9 (Gravel Removal), 10 (Debris Removal), 11 (Temporary Ford), 12 (Bank Erosion Protection), 13 (Culvert), 14 (Debris Removal), 21 (Gravel Removal)

Permit: 100123655

Permit Holder: Trans Mountain Pipeline ULC

_____

Authorized by BCER