Inspection Report

Permit Holder: Trans Mountain Pipeline ULC
Inspection: 2026-3563
Inspection Date: 2026-10-08
Inspection Outcome: Inspected

Inspection Comment:
BCER conducted an inspection of Trans Mountain Pipeline ULC changes in and about a stream works in the Merritt area.

Inspection items:

* Clapperton Creek - Observed completed works at Clapperton Creek area where a previous depth of cover integrity issue was identified. Trans Mountain Environmental Planner showed and discussed the engineered plans to restore DoC, reduce future erodibility potential and restore fish habitat with weirs. Observed gray water pump off location, no concerns. All disturbed areas had been recontoured and seeded. Noted that the area sees a high volume of livestock tramppling and that revegetation efforts will be difficult. Creek was observed to be flowing clean at time of inspection.
* 1kp841 - remediation efforts ongoing after a hydrocarbon plume was identified during mainline construction. Plume has been spatially identified and monitored. Excavation is underway. Small portion of adjacent wetland has been stripped, and soils are labeled and segregated. Silt fence utilized along wetland boundary to deter any deleterious material deposition into the wetland.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100116695
CIAS Number: 0007967
Location ID (Crossing Type): 1 (Matting), 2 (Open Cut)

Permit: 100122823
CIAS Number: 0010990
Location ID (Crossing Type): 1 (Bank Erosion Protection)

Permit: 100116695

Permit Holder: Trans Mountain Pipeline ULC

Authorized by BCER