Inspection Report

Permit Holder: Trans Mountain Pipeline ULC
Inspection: 2026-3564
Inspection Date: 2026-10-09
Inspection Outcome: Inspected

Inspection Comment:
BCER conducted an inspection of Trans Mountain Pipeline ULC pipeline integrity and changes in and about a stream works in the North Thompson corridor.

Inspected items:

* 1kp710 - previously identified integrity issue adjacent to watercourse. Dam and pump measures were in place at time of construction. Minor works completed to restore streambanks and channel flow after disturbance. Discussed with Trans Mountain Environmental Planner wattle placement within channel and small amounts of garbage left on site. Follow up provided by Trans Mountain: wattle keyed in and extended where necessary and garbage cleaned up. Water flowing clean at time of inspection.
* 1kp658.501 - Integrity dig adjacent to stream channel. Dam and pump measures were on site, but not necessary during construction. Stripped area up to edge of channel, but no disturbance required for any instream works. Stripped area had been reclaimed and vegetation observed throughout. Wattles placed adjacent to streambank as further protection.
* 1kp629.369 s3 Avola - Integrity dig adjacent to fish bearing watercourse. Topsoil stripped back directly adjacent to watercourse, dam and pump measures on site if needed during construction. No instream works were necessary during construction activities. ECB and wattles utilized for topsoil stabilization over disturbed areas and streambank erosion protection.
* 1kp577.571 s6 - integrity dig access required crews to air bridge the s6. Restoration of all disturbed areas completed. No instream works required. ECB used to stabilize topsoil and all disturbed areas were seeded.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100122813
CIAS Number: 0010865
Location ID (Crossing Type): 1 (Open Cut)

Permit: 100122910
CIAS Number: 0010904
Location ID (Crossing Type): 1 (Open Cut)

Permit: 100084645

Permit: 100122813

Permit: 100122910

Permit Holder: Trans Mountain Pipeline ULC

_____

Authorized by BCER