Inspection Report

Permit Holder: Trans Mountain Pipeline ULC
Inspection: 2026-3584
Inspection Date: 2026-10-13
Inspection Outcome: Inspected

Inspection Comment:

BCER conducted an inspection of Trans Mountain Pipeline ULC road infrastructure and road deactivation works in the Valemount and Blue River areas.

Inspected items:

* 2kp496.000 2 segments (3&4) inspected under Road #06288. Segment 3 deactivated, berm used as access control. Segment 4 not deactivated, flume/culvert left in watercourse under road. Gate observed at Hargreaves Road crossing. Condition 63(b) of permit not met and leave not granted by BCER.
* kp502.000 road 2F. Road #04615, segment 007. Evidence of recreational use of road present. Road deactivated.
* kp498.500 road 2H. Road #04615, segment 005. Discussed with Trans Mountain EI how the road, as it was laid out in the permit, was never built. Opted for use of the RoW as travel lane instead. No barricade present. Road deactivated.
* kp512.250 Road #04615, segment 013. Road not built. Some evidence of clearing for a short distance, but no other disturbance. Road deactivated.
* kp591.900 off Miledge FSR. Road # 04615, segment 091. Barricades in place, road reclaimed and deactivated.
* 2kp596A (Thunder Road). Road #04615 segment 094. Reclaimed portion leading to valve site, adjacent to highway rest area. Access control present. Road deactivated.
* Self reported non compliance Access 00171388 AD100101505 inspected.. Near Camp Creek. Evidence of recreational use on road. No barricade present, road active at time of inspection and observations forwarded to enforcement staff.
* Inspected CIAS culvert and road work along the Hargreaves Road intersection (near kp488). Trans Mountain EI explained the ongoing flooding issues associated with portion of the road and the work they have done to mitigate. New, elevated road surface and multiple, larger culverts installed along this segment. Gate present at entrance.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100101505
Road Number: 04615
Segment IDs (Location): 005 (From NTS: C- 056-K/083-D-14 To NTS: A- 058-K/083-D-14), 007 (From NTS: D- 042-L/083-D-14 To NTS: C- 041-L/083-D-14), 007 (From NTS: D- 042-L/083-D-14 To NTS: C- 041-L/083-D-14), 013 (From NTS: B- 054-F/083-D-14 To NTS: B- 065-F/083-D-14), 013 (From NTS: B- 054-F/083-D-14 To NTS: B- 065-F/083-D-14), 091 (From NTS: B- 016-B/083-D-06 To NTS: B- 016-B/083-D-06), 091 (From NTS: B- 016-B/083-D-06 To NTS: B- 016-B/083-D-06), 094 (From NTS: A- 078-J/083-D-03 To NTS: A- 078-J/083-D-03), 094 (From NTS: A- 078-J/083-D-03 To NTS: A- 078-J/083-D-03)

Permit: 100114772
Road Number: 06288
Segment IDs (Location): 003 (From NTS: D- 066-K/083-D-14 To NTS: D- 066-K/083-D-14), 004 (From NTS: D- 066-K/083-D-14 To NTS: D- 066-K/083-D-14)

Permit: 100101505
AACT Number: 00171388
Site Type: Access

Permit: 100101505
CIAS Number: 0004002
Location ID (Crossing Type): 2 (Culvert), 3 (Culvert)

Permit Holder: Trans Mountain Pipeline ULC

_____

Authorized by BCER