Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3595
Inspection Date: 2026-10-30
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Observations;

The Sirius chemical skids are compliant in their set up.

a-G-97 separator-the packing on the condi dump valve is starting to weep grease and should be attended to.

The SCVs seemed to be okay with none piped into secondary containment. Only well a-G-97-L has a SCV burst plate installed.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100114333
Facility ID: 00027409
Facility Name: PETRONAS BLUEBERRY A-097-L/094-A-12 001
Facility Type: Well Facility
Location: NTS: A- 097-L/094-A-12

_____

Authorized by BCER