Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3612
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
WA# 4167 - Nov. 4, 2026: 12:02 hrs. on site.

Wellhead: SCVA gate valve handle is in the open position; CANLIN is monitoring/reporting SCVF to standards.

The wellhead production status is suspended of which the flowlines are disconnected, and the majority of the upper well valve handles are chained and locked (3x). Note: the lower master/wing well valve handles (5x) were not chained and locked at the time of the inspection (all well valve handles must be disabled (chained/locked or removed).

Kermit last reported gas production rate: 2023-07 (Suspended Status).

Signage is compliant to standards.

Well Facilities: Out of Service

Storage: none on site.

Flowline: flowline is not connected to wellhead, well building flowline valve closed and disconnected to pipeline.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100005914
Well ID: 04167
Well Name: CANLIN CLARKE D- 096-L/094-J-09
Location: NTS: D- 096-L/094-J-09

Permit: 100005914
Facility ID: 00018740
Facility Name: CANLIN CLARKELAKE D-096-L/094-J-09 001
Facility Type: Well Facility
Location: NTS: D- 096-L/094-J-09

Authorized by BCER