Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3613
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
WA# 8867 - Nov. 4, 2026, 12:46 hrs. on site.

Wellhead: SCVA (2x) valve is found in the open position, no LEL was measured (Altair-5x), and no flow observed. Wellhead flowlines are disconnected and well valve handles are chained and locked.

KERMIT most recent gas production date: 2026-04 (Suspended Status).

Signage is compliant to standards.

Well Facility: Out of Service.

Flowlines: flowlines are disconnected to well, well building, and pipeline (Suspended Status).

Storage: no chemical storage tank is found on site.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016261
Well ID: 08867
Well Name: CANLIN CLARKE A- 005-A/094-J-15
Location: NTS: A- 005-A/094-J-15

Permit: 100016261
Facility ID: 00019156
Facility Name: CANLIN CLARKELAKE A-005-A/094-J-15 001
Facility Type: Well Facility
Location: NTS: A- 005-A/094-J-15

Permit: 100016703
Pipeline Project ID: 000006286
Segment IDs (Location): 1 (From NTS: A- 005-A/094-J-15 To NTS: C- 083-I/094-J-10)

Authorized by BCER