Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3622
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1133HRS.

Access road-Frozen access. Vegetation and light snow on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation & snow on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Well appears active. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Surface casing vent flow test- Minor Flow detected (low risk).

Meter building entry test- No alarms on personal monitor. Meter calibration tags up to date. No concerns at time of inspection.

Tanks on site-Out of service. No concerns at time of inspection.

Flare on site-Out of service. Positive isolation from flowline (Spec blind). No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100017081
Well ID: 09239
Well Name: CANLIN ET AL LAPRISE B- 099-F/094-H-05
Location: NTS: B- 099-F/094-H-05

_____

Authorized by BCER