Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-3673
Inspection Date: 2026-11-11
Inspection Outcome: Inspected

Inspection Comment:
Inspection Overview

Site 14-11-079-15 was inspected at approximately 1140 hours. Conditions were overcast with a temperature of 6°C.
Inspection Results
• Access and signage: Signage was clear and easy to read.
• Site condition: The wellsite was clean, with no vegetation-related concerns.
• Wellheads: Bull plugs, SCV, locks, and potential leaks were inspected. No SCV flow was detected, and all critical valves were locked. No concerns were identified.
• Meter/separator buildings: Locks, leaks, caps, and vents were inspected. No concerns were identified.
• Chemical tanks: Tanks were checked for leaks and inspected for proper grounding. No concerns were identified.
• Riser and pig stations: Chains and grounding were inspected. No concerns were identified.
• Associated pipelines: Vegetation cover along the pipelines was well established.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100071490
Well ID: 26475
Well Name: ARCRES HZ DAWSON 14-11-079-15
Location: DLS: 14-11-079-15

Permit: 100071491
Well ID: 26476
Well Name: ARCRES HZ DAWSON A14-11-079-15
Location: DLS: A14-11-079-15

Permit: 100071490
Facility ID: 00024708
Facility Name: ARCRES HERITAGE 14-11-079-15 001
Facility Type: Well Facility
Location: DLS: 14-11-079-15

Permit: 100071491
Facility ID: 00024709
Facility Name: ARCRES HERITAGE 14-11-079-15 002
Facility Type: Well Facility
Location: DLS: 14-11-079-15

Permit: 100072074
Pipeline Project ID: 000022209
Segment IDs (Location): 1 (From DLS: 14-11-079-15 To DLS: 11-14-079-15), 2 (From DLS: 11-14-079-15 To DLS: 14-11-079-15)

Permit Holder: ARC Resources Ltd.

_____

Authorized by BCER