Inspection Report

Permit Holder: Tidewater Midstream and Infrastructure Ltd.
Inspection: 2026-3701
Inspection Date: 2026-11-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Access road good, signage is present and lease is free of debris but is overgrown. ESD(s) and scv(s) at wellhead good. Chem tank(s) and secondary containment and pigging station(s) are good.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055651
Well ID: 21550
Well Name: TIDEWATER KELLY A- 009-J/093-P-01
Location: NTS: A- 009-J/093-P-01

_____

Authorized by BCER