Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3754
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Inspection Overview
Site 02-32-081-15 was inspected at approximately 1225 hours. Conditions were sunny with a temperature of 3°C.

Inspection Results
• Access and signage: Signage was clear and easy to read.
• Site condition: The wellsite was clean, with no vegetation-related concerns.
• Wellheads: Bull plugs, SCV, locks, and potential leaks were inspected. No SCV flow was detected, and all critical valves were locked. No concerns were identified.
• Meter/separator buildings: Locks, leaks, caps, and vents were inspected. No concerns were identified.
• Chemical tanks: Tanks were checked for leaks and inspected for proper grounding. No concerns were identified.
• Riser and pig stations: Chains and grounding were inspected. No concerns were identified.
• Associated pipelines: Vegetation cover along the pipelines was well established.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038681
Well ID: 16710
Well Name: CANLIN ET AL PARKLAND 02-32-081-15
Location: DLS: 02-32-081-15

Permit: 100038681
Facility ID: 00020362
Facility Name: CANLIN PARKLAND 02-32-081-15 001
Facility Type: Well Facility
Location: DLS: 02-32-081-15

Permit: 100043507
Pipeline Project ID: 000013465
Segment IDs (Location): 1 (From DLS: 02-32-081-15 To DLS: 06-29-081-15), 2 (From DLS: 06-29-081-15 To DLS: 02-32-081-15)

Permit Holder: Canlin Energy Corporation

_____

Authorized by BCER