Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-3797
Inspection Date: 2026-11-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Proximity to Risk & Data Informed Inspection on road and bridge.

Performed inspection of area at 1503HRS.

Access Road- Frozen access, Road has minor tire rut marks. Vegetation is not overgrown or impeding visibility. No concern at time of inspection.

Bridge- Signage in place (up & down) that warns of narrowing bridge, partially obstructed by branches (See attached). Reflective markers are missing on each corner of bridge (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100108292
Road Number: 05364
Segment IDs (Location): 001 (From NTS: D- 032-B/094-H-02 To NTS: D- 035-B/094-H-02)

_____

Authorized by BCER