Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3824
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Access opportunity inspection of surface equipment on site.

Performed inspection of location at 1327HRS.

Access road- Vegetation growing on access road. Frozen Access Only. Ruts formed from water drainage, along access to surface equipment (See attached). No concerns at the time of inspection.

Lease environment- Vegetation on lease. Ruts and trenches formed from water drainage around location (See attached). Officer was unable to determine if lease sediment is flowing off lease, and will continue to monitor area.

Lease Equipment- Wellhead Suspended. Wellhead located in building. Building entry test- No alarms on personal monitor. Building out of service. Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected.

Tanks and secondary containment on site-No concerns at time of inspection.

Note: various damaged equipment laying on ground around location (See attached).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100049766
Well ID: 19970
Well Name: CNRL DAHL A- 062-H/094-H-07
Location: NTS: A- 062-H/094-H-07

_____

Authorized by BCER