Inspection Report

Permit Holder: Aduro Resources Ltd.
Inspection: 2026-3834
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Signage no concerns.

SCV's no venting observed.

Both wellheads are isolated and chained in the locked position.

Site is not in operation.

No other concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040833
Well ID: 16535
Well Name: ADU HZ MONIAS 05-07-082-22
Location: DLS: 05-07-082-22

Permit: 100055329
Well ID: 21416
Well Name: ADU MONIAS A05-07-082-22
Location: DLS: A05-07-082-22

Permit: 100040833
Facility ID: 00020313
Facility Name: ADU MONIAS 05-07-082-22 001
Facility Type: Well Facility
Location: DLS: 05-07-082-22

Authorized by BCER