

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.

Discovery Date: 2026-09-23

As a result of Inspection 2026-3422

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0653-01 Issued Date: '2026-09-28' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-10-12'	Permit: 100120812 Well ID: 55290 Well Name: PETRONAS HZ TOWN D-R066-J/094-B-16 Location: NTS: D-R066-J/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: The lower master valve was observed dripping produce water from the valve stem. The produced water then formed crystals on the tubing hanger below.	

Non-Compliance Number: 2026-0653-02 Issued Date: '2026-09-28' Status: Issued Outcome: Correction Duration: 14 Days	Permit: 100114680 Well ID: 44090 Well Name: PETRONAS HZ TOWN D-O066-J/094-B-16 Location: NTS: D-O066-J/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
---	--

Correction Due Date: '2026-10-12'	
Non-Compliance Comment: The hose from the surface casing vent into the containment tank is leaking liquid at the steel gooseneck and both ends of the fitting.	

Authorized by BCER