

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-09-23
As a result of Inspection 2026-3425

Notice Comment:

The annulus valve stem is leaking.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0654-01 Issued Date: '2026-09-29' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-10-13'	Permit: 100055912 Well ID: 21665 Well Name: PETRONAS TOWN C- 049-J/094-B-16 Location: NTS: C- 049-J/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: The annulus valve stem is leaking.	

Authorized by BCER