

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-09-23
As a result of Inspection 2026-3428

Notice Comment:

The isolation valve for the well head ESD pilot is not locked in the open position.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0656-01 Issued Date: '2026-09-29' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-10-13'	Permit: 100070590 Well ID: 26057 Well Name: CNRL ET AL HZ BLAIR A-A050-F/094-B-16 Location: NTS: A-A050-F/094-B-16 Legislation: Drilling and Production Regulation 49 (2) Subject to subsection (1), a permit holder must lock or car seal any valve or device that can bypass or disable safety equipment at a well that is producing, injecting or disposing of fluids, or at a facility.
Non-Compliance Comment: a-a-50-F well--the isolation valve for the well head ESD pilot is not locked in the open position.	

Authorized by BCER