

Non-Compliance Notice - Issued

Permit Holder: Lakota Operating Company Inc.

Discovery Date: 2026-10-01

As a result of Inspection 2026-3441

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0664-01 Issued Date: '2026-10-02' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-10-31'	Permit: 100016025 Well ID: 08793 Well Name: LAKOTAOP TALLAHASSEE W FLATROCK 04-16-085-17 Location: DLS: 04-16-085-17 Legislation: Drilling and Production Regulation 15 (1) Until the well is abandoned, a well permit holder must ensure that a permanently legible and conspicuous sign is displayed and maintained at each well, and that sign must show all of the following: (a) the name of the well permit holder;
Non-Compliance Comment: the location signage still has the Permit Holder name as "Tallahassee", -also missing the flammable symbol, -emergency number is not the Lakota Emergency number but did ring through to a Tax Consultant voicemail...?? -sour symbol is faded. After looking at the last gas analysis submission for this well on file from 1995, it shows no H2S in gas stream. Therefore, no sour symbol should be on location signage, if this submission still stands correct.	

Authorized by BCER