

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-10-01
As a result of Inspection 2026-3458

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0669-01 Issued Date: '2026-10-08' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-10-22'	Permit: 100108830 Well ID: 39501 Well Name: PETRONAS HZ TOWN C-F021-J/094-B-16 Location: NTS: C-F021-J/094-B-16 Legislation: Drilling and Production Regulation 18 (9) A well permit holder must ensure that a well is configured such that (c) the surface casing is equipped with an open valve.
Non-Compliance Comment: The SCV ball valve is in the closed position.	

Non-Compliance Number: 2026-0669-02 Issued Date: '2026-10-08' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date:	Permit: 100114213 Well ID: 42802 Well Name: PETRONAS HZ TOWN C-N021-J/094-B-16 Location: NTS: C-N021-J/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
--	--

'2026-10-22'	
Non-Compliance Comment: The surface casing vent is expelling liquids as evident by fluid on SCV piping, well head and the ground. The SCV needs to have containment as well as this liquid component needs to be reported to BCER Engineering in Kelowna thru your regular channels of reporting SCV leaks.	

Authorized by BCER