

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.

Discovery Date: 2026-10-02

As a result of Inspection 2026-3476

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0673-01 Issued Date: '2026-10-13' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-10-27'	Permit: 100109898 Well ID: 40074 Well Name: PETRONAS HZ GUNDY CREEK WEST D-G082-J/094-B-09 Location: NTS: D-G082-J/094-B-09 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: The valve stem is leaking produced water as per the evidence of precipitate.	

Non-Compliance Number: 2026-0673-02 Issued Date: '2026-10-13' Status: Issued Outcome: Correction Duration: 14 Days	Permit: 100109898 Well ID: 40075 Well Name: PETRONAS HZ GUNDY CREEK WEST D-H082-J/094-B-09 Location: NTS: D-H082-J/094-B-09 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
---	--

Correction Due Date: '2026-10-27'	
Non-Compliance Comment: The valve stem on the wellhead choke is leaking produced water as evident by the build up of crystals.	

Authorized by BCER