

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-10-13
As a result of Inspection 2026-3507

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0678-01 Issued Date: '2026-10-20' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-11-03'	Permit: 100078843 Facility ID: 00017884 Facility Name: PETRONAS GUNDY CREEK D-007-H/094-B-16 001 Facility Type: Well Facility Location: NTS: D- 007-H/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: There is LEL in the BU 8000 lift gas skid.	

Non-Compliance Number: 2026-0678-02 Issued Date: '2026-10-20' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date:	Permit: 100078843 Facility ID: 00017884 Facility Name: PETRONAS GUNDY CREEK D-007-H/094-B-16 001 Facility Type: Well Facility Location: NTS: D- 007-H/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
--	---

'2026-11-03'	
Non-Compliance Comment: There is LEL in the lift gas skid, BU 9000.	

Authorized by BCER