Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-10-29
As a result of Inspection2026-3575

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0692-01** Issued Date: **'2026-11-01'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-11-15'**	Permit: 100106618 Well ID: 38020 Well Name: PETRONAS HZ TOWN A-A002-H/094-B-16 Location: NTS: A-A002-H/094-B-16 Legislation: Drilling and Production Regulation 16 (1) A well permit holder must ensure (a) that all tools and equipment used in well operations, production, injection or disposal are installed and operated in accordance with the manufacturer's specifications or sound engineering practices,

Non-Compliance Comment: A Petronas Operator was on their way to this location so I informed him of some
deficiencies / concerns. He was going to install the bull plug which was
missing from a needle valve located on a flange 2 elbows downstream of the well
head choke.

Non-Compliance Number: **2026-0692-02** Issued Date: **'2026-11-01'** Status: **Issued** Outcome:	Permit: 100106618 Well ID: 38021 Well Name: PETRONAS HZ TOWN A-B002-H/094-B-16 Location: NTS: A-B002-H/094-B-16 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;

Correction Duration: **30 Days** Correction Due Date: **‘2026-12-01‘**	
Non-Compliance Comment: The grease gun on the orifice plate changer is weeping produced water.	

_____

Authorized by BCER