Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-10-30
As a result of Inspection2026-3594

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0693-01** Issued Date: **'2026-11-03'** Status: **Issued** Outcome: Correction Duration: **30 Days** Correction Due Date: **'2026-12-03'**	Permit: 100110675 Facility ID: 00027166 Facility Name: PETRONAS BLUEBERRY D-028-D/094-A-13 001 Facility Type: Well Facility Location: NTS: D- 028-D/094-A-13 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: The lift gas meter building has high LEL. Did not enter.	

Non-Compliance Number: **2026-0693-02** Issued Date: **'2026-11-03'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date:	Permit: 100107623 Well ID: 38558 Well Name: PETRONAS HZ BLUEBERRY D-F028-D/094-A-13 Location: NTS: D-F028-D/094-A-13 Legislation: Drilling and Production Regulation 53 A permit holder must ensure all of the following: (e) if natural gas, petroleum, natural gas liquids, natural gas byproducts or water are produced from or injected into a well or facility, that (i) the meter is maintained in good operating condition, and

‘2026-11-17‘	
Non-Compliance Comment: d-F-28 well facility- The last meter calibration was done in 2024 and is over due. The orifice plate was inspected in Sept 2026. Please check all of your meter runs for currency in calibration and orifice plate inspections as there is some inconsistency.	

_____

Authorized by BCER