Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-10-30
As a result of Inspection2026-3595

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0694-01** Issued Date: **'2026-11-03'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-11-17'**	Permit: 100114333 Facility ID: 00027409 Facility Name: PETRONAS BLUEBERRY A-097-L/094-A-12 001 Facility Type: Well Facility Location: NTS: A- 097-L/094-A-12 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;

Non-Compliance Comment: The joint meter skid for a-97-L and a-a-97-L has LEL. Did not proceed with inspection after atmosphere check failed.

Non-Compliance Number: **2026-0694-02** Issued Date: **'2026-11-03'** Status: **Issued** Outcome: Correction Duration: **14 Days**	Permit: 100114333 Facility ID: 00027409 Facility Name: PETRONAS BLUEBERRY A-097-L/094-A-12 001 Facility Type: Well Facility Location: NTS: A- 097-L/094-A-12 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;

Correction Due Date: **'2026-11-17'**	
Non-Compliance Comment: The joint well facility meter skid for a-B-97-L and a-C-97-L has LEL. Did not proceed with inspection after atmosphere check failed.	

Non-Compliance Number: **2026-0694-03** Issued Date: **'2026-11-03'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-11-17'**	Permit: 100114333 Facility ID: 00027409 Facility Name: PETRONAS BLUEBERRY A-097-L/094-A-12 001 Facility Type: Well Facility Location: NTS: A- 097-L/094-A-12 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: The joint well facility meter skid for a-D-97-L and a-e-97-L has LEL. Did not proceed with inspection due to atmosphere check failure.	

Non-Compliance Number: **2026-0694-04** Issued Date: **'2026-11-03'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date:	Permit: 100114333 Facility ID: 00027409 Facility Name: PETRONAS BLUEBERRY A-097-L/094-A-12 001 Facility Type: Well Facility Location: NTS: A- 097-L/094-A-12 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;

‘2026-11-17‘	

Non-Compliance Comment: There is LEL in the joint well facility meter skid for a-F-G-97-L and a-G-97-L.
Did not proceed with inspection due to failed atmosphere check.

Non-Compliance Number: **2026-0694-05** Issued Date: **‘2026-11-03’** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **‘2026-11-17‘**	Permit: 100114333 Facility ID: 00027409 Facility Name: PETRONAS BLUEBERRY A-097-L/094-A-12 001 Facility Type: Well Facility Location: NTS: A- 097-L/094-A-12 Legislation: Drilling and Production Regulation 53 A permit holder must ensure all of the following: (e) if natural gas, petroleum, natural gas liquids, natural gas byproducts or water are produced from or injected into a well or facility, that (i) the meter is maintained in good operating condition, and

Non-Compliance Comment: a-F-97-L well facility -The last meter and orifice plate inspection was done in
2022 and is long overdue. The same goes for a-G-97-L well facility. Pease check
all meter run calibrations and orifice plate inspections as there are more that
need servicing.

_____

Authorized by BCER