Non-Compliance Notice - Issued

Permit Holder: NTE Energy Canada Ltd.
Discovery Date: 2026-11-09
As a result of Inspection2026-3637

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0703-01** Issued Date: **'2026-11-11'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-11-25'**	Permit: 100034252 Pipeline Project ID: 000010894 Segment IDs (Location): 3 (From NTS: A- 098-B/094-P-04 To NTS: C- 095-B/094-P-04) Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and

Non-Compliance Comment: Pipeline low drain ball valve (at pig enclosure) is missing a bull plug to prevent spillage.

Note: Plastic cover on pig barrel containment (catchment/plastic tub) is not secured/attached to the basin.

Non-Compliance Number: **2026-0703-02** Issued Date: **'2026-11-11'** Status: **Issued** Outcome:	Permit: 100034252 Pipeline Project ID: 000010894 Segment IDs (Location): 3 (From NTS: A- 098-B/094-P-04 To NTS: C- 095-B/094-P-04) Legislation: Pipeline Regulation 3 (1) Subject to subsection (2), a pipeline permit holder must not design, construct, operate or maintain any of the following except in accordance with CSA Z662:

Correction Duration: **14 Days** Correction Due Date: **‘2026-11-25‘**	(a) the pipeline that is the subject of the permit;
Non-Compliance Comment: Pipeline pig barrel enclosure safety chains are not attached to pressure assist valves (3x).	

_____

Authorized by BCER