Non-Compliance Notice - Issued

Permit Holder: ConocoPhillips Canada Resources Corp.
Discovery Date: 2026-11-09
As a result of Inspection2026-3647

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0705-01** Issued Date: **'2026-11-12'** Status: **Issued** Outcome: Correction Duration: **30 Days** Correction Due Date: **'2026-12-12'**	Permit: 100108348 Well ID: 39174 Well Name: COP HZ INGA D01-31-088-23 Location: DLS: D01-31-088-23 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: Fitting on orific plate audibly hissing & frosted over, LEL alarm in close proximity (See attached)	

Non-Compliance Number: **2026-0705-02** Issued Date: **'2026-11-12'** Status: **Issued** Outcome: Correction Duration: **14 Days**	Permit: 100108348 Well ID: 39175 Well Name: COP HZ INGA E01-31-088-23 Location: DLS: E01-31-088-23 Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and

Correction Due Date: **'2026-11-26'**	
Non-Compliance Comment: Missing cap on gas meter fitting (see attached).	

_____

Authorized by BCER