Non-Compliance Notice - Issued

Permit Holder: Harvest Operations Corp.
Discovery Date: 2026-11-18
As a result of Inspection2026-3711

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0717-01** Issued Date: **'2026-11-19'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-12-03'**	Permit: 100076617 Facility ID: 00025710 Facility Name: HARVEST HAYRIVER A-005-G/094-I-09 002 Facility Type: Well Facility Location: NTS: A- 005-G/094-I-09 Legislation: Drilling and Production Regulation 49 (2) Subject to subsection (1), a permit holder must lock or car seal any valve or device that can bypass or disable safety equipment at a well that is producing, injecting or disposing of fluids, or at a facility.

Non-Compliance Comment: Valve on Pressure pilot for ESD is not secured with clamshell, carseal or lock.
Discussed with Harvest Field Operator working in the area.

_____

Authorized by BCER